


Appendix 3 NT model conversion sequence list (NT-series Screen Data Conversion)

Revised on 2002/04/15




\* 1 : NT600G support software is required to transfer data from the hardware NT600G.

An applicable PC is old NEC personal computers. (Refer to Operation Manual.)

○ : The support software above is included with “NT-Series Electric Catalog CD-ROM” *NT Museum – NT-Series Chronological Table – Support Tool Download.*

○ : Screen adjustment may be necessary after conversion between different models, affected by the differences in touch SW mesh size or No. of dots on the screen.


○ : Allocation is required when direct access is changed from “Not available” to “Available”. (DOS: NTS Operation Manual)



Note : When a Large screen model is converted to a smaller screen mode, any part that is out of the screen will be deleted.

\*\* : Only the screen data of Ver.5 can be transferred from NT20S/600S using NTST.

Screen data of Ver.4 can be transferred using DOS NTS.



- (1) Any functional objects out of the screen frame will be deleted when converting data from NT631/C to NT31/C
- (2) System programs are optionally replaceable.

